

Fire Safety Report

Residential Facility Address*	Fire Alarm Monitoring Done On Site#	Full Sprinkler System	Smoke Detection	Fire Extinguisher Devices	Evacuation Plans & Placards	# of Fire Drills Per Calendar Year	Fires in 2018
Fischer Hall 8890 W. Bluemound Rd.	Yes	Yes	Yes	Yes	Yes	3	0
Stimac Hall 8780 W. Bluemound Rd.	Yes	Yes	Yes	Yes	Yes	3	0
Aspire Hall 8901 W. Wisconsin Ave.	Yes	Yes	Yes	Yes	Yes	3	0
541 N. 89th St.	No	No	Yes	Yes	Yes	1	0
555 N. 89th St.	No	No	Yes	Yes	Yes	1	0
603 N. 89th St.	No	No	Yes	Yes	Yes	1	0
611 N. 89th St.	No	No	Yes	Yes	Yes	1	0
619 N. 89th St.	No	No	Yes	Yes	Yes	1	0
627 N. 89th St.	No	No	Yes	Yes	Yes	1	0
511 N. 90th St.	No	No	Yes	Yes	Yes	1	0
540 N. 90th St.	No	No	Yes	Yes	Yes	1	0
630 N. 90th St.	No	No	Yes	Yes	Yes	1	0
8616 W. Bluemound Rd.	No	No	Yes	Yes	Yes	1	0
8624 W. Bluemound Rd.	No	No	Yes	Yes	Yes	1	0
8710 W. Bluemound Rd.	No	No	Yes	Yes	Yes	1	0
8716 W. Bluemound Rd.	No	No	Yes	Yes	Yes	1	0
9114 W. Bluemound Rd.	No	No	Yes	Yes	Yes	1	0
9128 W. Bluemound Rd.	No	No	Yes	Yes	Yes	1	0
8619 W. Wisconsin Ave.	No	No	Yes	Yes	Yes	1	0
8625 W. Wisconsin Ave.	No	No	Yes	Yes	Yes	1	0
8629 W. Wisconsin Ave.	No	No	Yes	Yes	Yes	1	0
8633 W. Wisconsin Ave.	No	No	Yes	Yes	Yes	1	0
9021 W. Wisconsin Ave.	No	No	Yes	Yes	Yes	1	0
505 Maywood Ct.	No	No	Yes	Yes	Yes	1	0
520 Maywood Ct.	No	No	Yes	Yes	Yes	1	0

*All addresses in Milwaukee/Wauwatosa, WI 53226

#Public Safety automatically notified by fire detection system if checked "Yes"